

OSA - 1878-70

A12  
7322

26 June 1970

3

25X1

Subject: Contract [REDACTED] (657)-12846 Follow-On EMR  
Monthly Technical Progress Report  
Period Ending 31 May 1970

Dear Burt:

In fulfillment of the subject obligation enclosed please  
find one (1) copy of this Contractor's report No. 75.

Regards,



Jim

STATINTL

JM:vg  
Encl.  
cc: SPO [REDACTED]

ASPO

2 cys. encl.  
encl.

ELECTROMAGNETIC RECONNAISSANCE SYSTEMS

MONTHLY LETTER REPORT NO. 75 (U)

1940-L-75

PERIOD ENDING: 31 MAY 1970

This is the seventy-four (74) monthly letter report listing the remaining open items attendant to the procurement of additional Electromagnetic Reconnaissance Systems (EMR). (March 1970)

FOLLOW-ON EMR PROGRAM-STATUS OF OUTSTANDING ITEMS

BASIC CONTRACTUAL OBLIGATIONS

W/S Item V - CONFIGURATION RECORDS

Will be submitted for acceptance under the Contractor's final (close-out) voucher.

Complete - Not delivered

SUPPLEMENTARY CONTRACTUAL REQUIREMENTS

ECP 1940-29 SCL MEMORY NOISE & LOGIC RETROFIT

One (1) remaining spare assembly "Stabilizers and STATINTL Drive Assemblies Wired" (TI P/N 542064-2, EMI 902720A02) is in the process of being modified by the Subcontractor, [redacted]

[redacted] - This item had a contemplated delivery to AI of 15 July 1970. (\*)

(\*) On 24 June 1970 [redacted] reported that testing on STATINTL the Stabilizer & Drive Ass'y is proceeding without problems & the unit is now scheduled for delivery to [redacted] on 30 June 1970. Delivery to PSO should follow within a week to ten (10) days thereafter.

APPROVED: [redacted]

OPTIONAL REQUIREMENTS (Spare Parts)

<u>LIST NO.</u>	<u>SEQ. #</u>	<u>PT. NO.</u>	<u>NOMENCLATURE</u>	<u>QTY</u>	<u>REMARKS</u>	<u>EDD</u>	<u>SHIP INFORMA.</u>	
-1		A09320	340500-1	Stage & Amp Assem.	1		2/70	Vo.5201 to PSO
4		024600	542065-1	Sense Card Assem.	1	ASPO enters this item on DCN E67-147 S/B List 4 I/N 024600	7/15/70 (*)	
-4		023401	542064-2	Stabilizer Assem.	1	ASPO enters P/N as 542064-1 on DCN E68-16. S/B P/N 542064-2 DCN E68-91 See List 4 I/N 023401	1/70	Vo.5108 to PSO
36		700181	502487-4	One Shot L.C.	2		4/70	Vo.5313 to PSO
36		700182	502487-3	One Shot L.C.	2		4/70	Vo.5313 to PSO

(\*) Per telecon discussion with [ ]

STATINTL

[ ] on 24 June 1970  
[ ] this subcontractor has encountered  
problems with the Sense Amplifier.

[ ] has reported that they are experiencing  
too fast a rise time with transistors  
that have been recently procured -  
Complete manufacture of new modules may  
be required. [ ] is forwarding  
correspondence to [ ] stating the overall  
impact.

STATINTL  
STATINTL

STATINTL

STATINTL